












Lindhus-U shape










**Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Сервисная служба**


| | | | | | | |
|---|--|----|-----|-----|-----|--|
| Name • Nom • Nome • Naam Nazwa • Jméno • Název • Név Denumire • Ísim • Название | | | | | | |
| Nr. • No. • N° • Номер • Č • Sz | | | | | | |
| Typ • Type • Tip • Típus • Тип Тип | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | 1/3 | 2/3 | 3/3 | |
| AX4 | | X2 | X1 | X1 | | |
| BX1 | | | √ | | | |
| CX2 | | X1 | | | X1 | |
| DX1 | | | √ | | | |
| EX1 | | √ | | | | |
| FX2 | | | | X1 | X1 | |
| GX4 | | X2 | X1 | X1 | | |
| HX12 | | | | X8 | X4 | |
| IX1 | | | | √ | | |
| JX2 | | | | X1 | X1 | |
| KX1 | | | | √ | | |
| LX8 | | | | √ | | |

| | | | 1/3 | 2/3 | 3/3 |
|------|---|--|-----|-----|-----|
| MX10 |  | | | X8 | X2 |
| NX4 |  | | | X2 | X2 |
| QX20 |  M6x25mm | | | X16 | X4 |
| RX6 |  M6x25mm | | | X5 | X1 |
| SX8 |  M6x35mm | | | √ | |
| TX2 |  | | | X1 | X1 |
| UX1 |  | | √ | | |







1




2




3




4




5




6




7



8



9



10

