





Lagos 79413

Lagos 79414



(D) Montageanleitung
79413 79414

(FR) Notice de montage
79413 79414

(NL) Handleiding voor de montage
79413 79414

(CZ) Montážní návod
79413 79414

(HU) Szerelési útmutató
79413 79414

(TR) Montaj talimatı
79413 79414

(GB) Assembly instructions
79413 79414




(IT) Istruzioni di montaggio
79413 79414

(PL) Instrukcja montażu
79413 79414

(SK) Návod na montáž
79413 79414

(RO) Instrucțiuni de montaj
79413 79414


(RU) Инструкция по монтажу
79413 79414






0
10
20
30
40
50
60
70
80
90
100
110
120
130
140
150
160
170
180
190
200






Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Сервисная служба


Name • Nom • Nome • Naam • Nazwa • Jméno • Názov • Név • Denumire • Ísim • Название	
Nr. • No. • N° • Номер • Č. • Sz	
Typ • Type • Tip • Típus • Tipo • Тип	
	











!	Achtung•Attention•Opgelet•Uwaga•Dikkat•	Внимание !
D	Ziehen Sie alle Schrauben sowie tragende Verbindungsteile nach ca. 5 Wochen nach, um eine dauerhafte Standsicherheit zu gewährleisten.	
GB	After approx. 5 weeks, tighten all screws and load-bearing connecting parts to ensure permanent stability.	
FR	Resserrez toutes les vis ainsi que les pièces de fixation au bout d'environ 5 semaines pour garantir une sécurité de fixation durable.	
IT	Ristringere tutte le viti e giunture dopo ca. 5 settimane, al fine di garantire una durevole solidità.	
NL	Draai alle schroeven en ook dragende verbindingstukken na ca. 5 weken nog eens vast, zodat een continue stabiliteit wordt gegarandeerd.	
PL	Prosimy po ok. 5 tygodniach dokręć cię wszystkie śruby w elementach łączeniowych. Zagwarantuje to Pań stwu trwałość i stabilność połączzeń.	
CZ	Dotáhněte všechny šrouby a nosné spojovací díly přibližně po 5 týdnech, aby se zaručila trvalá stabilita.	
SK	Po cca 4 týždňoch dotiahnite skrutky, aby bola zaručená ich trvalá stabilita.	
HU	Húzza utána - kb. 5 hét múlva - az összes csavart és a teherhordó összekötő -alkatrészeket a biztonság érdekében.	
RO	Pentru a asigura o stabilitate de durată, strângeți după cca. 5 săptămâni toate șuruburile, precum și toate elementele portante de legătură.	
TR	Tüm vida ve taşıyıcı bağlantı parçalarını kalıcı bir duruş güvenliğini sağlamak için yaklaşık 5 hafta sonra tekrar sıkınız.	
RU	Подкрутите все болты, а также несущие соединительные детали прибл. через 5 недель для обеспечения устойчивости в течение длительного времени.	